


October 12, 1987

TO: File

FROM: Frank Filas, Reclamation Engineer 

RE: Site Inspection, SM/015/036 - Brown Rose Mine
and SM/015/037 - Primrose 2

On October 12, 1987, I inspected the two above-referenced sites. The Brown Rose Mine looked much the same as was photographed one month earlier.

I could find no evidence of any surface disturbance near Tidwell Springs, where the Primrose 2 claim is located.

FF/jr
1312R/8